JBL Intonato 24 Control App

Version 1.1.9   September 7, 2017

Notes:

> Please note that this Software update also includes a Firmware update for the Intonato 24. The Firmware MUST be updated at this time by using the Firmware Updater located in the Settings menu. Please allow the Intonato 24 to perform a reboot after updating the Firmware. Do not power cycle the unit at any time during the Firmware update process.

Bug Fixes

- Conditions: Signal Generator is ON, all outputs are in OFF status, user creates a Device Backup file. User performs Device Restore using the Backup file, unit is restored with all outputs in OFF Status. User is unable to UN-MUTE the outputs. Factory Reset is required.