## **Display Messages EP1000**

Displayed message	Signal source	Solution	note
Err Gobo Wheel	Gobo wheel rotation hall sensor	Check hall sensor, gobo wheel	
		motor, connection, missing	
		magnet.	
Err Gobo ind/rot	Gobo Index rotation hall sensor	Check hall sensor, gobo index	
		rotation motor, connection,	
		missing magnet	
Err Frost Wheel	Frost rotation hall sensor	Check hall sensor, Frost motor,	
		connection, missing magnet	
Err Prism 1	Prism 1 Hall sensor. (Display side)	Check hall sensor, prism wheel	
		motor, connection, missing magnet	
Err Prism 2	Prism 2 hall sensor	Check hall sensor, prism wheel	
		motor, connection, missing magnet	
Err Prism ind/rot	Prism 1 and 2 index rotation Hal	Check hall sensor, prism wheel	
	sensor	motor, connection, missing magnet	
Err. PCBA Fan	Driver PCBA Fan is defect or the	Check Fan and Connection	
	connection is not OK		
Err. CMY Fan 1	CMY Fan 1 is defect or the connection	Check Fan and Connection	
	is not OK	Check Full and Connection	
Err. CMY Fan 2 Err. PSU Fan	CMY Fan 2 is defect or the connection	Check Fan and Connection	
	is not OK	Check Fair and Connection	
	PSU Fan is defect or the connection	Check Fan and Connection	
	is not OK	Check Fair and Connection	
Err. GOBO Wheel Fan Err Yellow	GOBO Wheel Fan is defect or the	Check Fan and Connection	
	connection is not OK	Check Fair and Connection	
	Yellow CMY hall sensor	Charleball annuar marker	
	Yellow Civit hall sensor	Check hall sensor, motor,	
Err Magenta	Adamada CAAV hall access	connection, missing magnet	
	Magenta CMY hall sensor	Check hall sensor, motor,	
		connection, missing magnet	
Err Cyan	Cyan CMY hall sensor	Check hall sensor, motor,	
		connection, missing magnet	
Err Color wheel	Color wheel Hall sensor	Check hall sensor, motor,	
		connection, missing magnet	
Err Focus	Focus hall sensor	Check hall sensor, motor,	
		connection, missing magnet	
Err Zoom	Zoom hall sensor	Check hall sensor, motor,	When Zoom hall sensor is removed the
		connection, missing magnet	product is sending out 3 messages:
			Err ch: Frost
			Err ch: Prism
			Err ch:
			Err Zoom
Err Animation Index	Animation indexing Hall sensor	Check hall sensor, motor,	
		connection, missing magnet	
Err Animation Rotation	Animation Rotation Hall sensor	Check hall sensor, motor,	
		connection, missing magnet	
		1	1